1. Get the latest Thunderbolt driver from MSI website
   Search for product page and click "Download" > the Thunderbolt driver update package is under the Driver tab.

2. Open the Device Manager, and make sure that a Thunderbolt Contorller device is shown under "System devices" (e.g. Thunderbolt™ Controller – 15D9).
   - If the thunderbolt controller device doesn't show in the device manager, reboot the system and press "delete" button to enter BIOS menu > Advanced > Thuderbolt firmware update, change the setting to "Enabled" and press "F10" to save configuration nad reset the system.

3. Extract the file installer package and open the folder.

4. Find and Select the Thunderbolt Driver installer folder "ThunderboltUwdSetup" or "ThunderboltDchSetup".

5. Right click on "TbtHostController.inf" and click "Install".

6. Click "OK" to close the window after the installation complete.

7. After installing the Thunderbolt Driver, enter another application launcher (ThunderboltApplicationLauncherSetup) folder.

8. Right click on "TbtHostControllerExtension.inf" and click "install".

9. After the files are installed, the driver installation process is complete.

10. Click here to download "Thunderbolt Control Center" in Microsoft Store.