



# DONNING ENHANCED CONTACT PRECAUTIONS PPE



EQUIPMENT: **A** SURGICAL GOWN, **B** SURGICAL HOOD, **C** FACE SHIELD, **D** EXTENDED CUFF PATIENT GLOVES (INNER), **E** BOOT COVERS, **F** N95 RESPIRATOR, **G** EXTENDED CUFF PATIENT GLOVES (OUTER), **H** BIOHAZARD WASTE RECEPTACLE.



**1** Hydrate. **2** Engage trained observer. **3** Remove all personal items. Tie back long hair. **4** Put on scrubs and washable footwear. **5** Take and record vital signs.



# DONNING ENHANCED CONTACT PRECAUTIONS PPE



**6** Inspect PPE supplies. Review donning sequence. **7** Perform hand hygiene.  
**8** Put on boot covers **9** Put on standard patient care gloves.




**10** Put on surgical gown. NOTE: ALL TIES should be properly secured with a SIMPLE BOW. Ensure gown fits well and covers inner glove cuffs. **11** Put on N95 respirator. Seal mask to face ensuring straps are not crossed and are properly located at the crown of the head and base of the neck. Perform a fit check of the respirator by breathing deeply in and out, feeling with your hands for any air leakage.





## DONNING ENHANCED CONTACT PRECAUTIONS PPE



**12** Put on surgical hood. **13** Apply long cuff patient gloves over the standard patient care gloves, covering sleeves fully to prevent exposure when providing patient care. **14** Apply face shield.



**15** Trained observer verifies all PPE properly fitted.

**!** If the patient's condition warrants, additional personal protective equipment may be added to these guidelines. This may include items such as Tyvek suits, powered air purifying respirators, and aprons. **!**