VPN compatibility issue with Microsoft Windows[®] 7 Windows Mobile Broadband



Description

With the introduction of software Update Version L0290VWBB12F.248 for the Pantech UML290, Windows 7 Mobile Broadband support was enabled, which caused the following issues.

Operating System Affected:

• Windows 7 and Windows 8

Known issues:

• Windows 7 Mobile Broadband support has caused problems with VPN connectivity due to some VPN solutions not being compatible with this new functionality.

List of known VPN clients:

- o Cisco VPN client
- $\circ \quad \text{Nortel VPN client}$

Connection errors such as Unknown Error (Code: 2107)

Work around:

With VZAccess Manager 7.7.7 (2767c) or higher, the modem operating mode can be changed from Windows 7 Mobile Broadband to LAN Adapter mode. This issue is eliminated when the modem is operating in LAN Adapter mode.

Instructions for VZAccess Manager:

- 1. Connect your modem.
- 2. Launch VZAccess Manager and verify the version matches the one referenced above by selecting "Help-> About VZAcces Manager."

VZAccess Manager		
File View Tools Options	Help	verizon
🖉 Networks 🛛 🛤 Statict	Contents F1	orations
T HECHOIRS Z Staust	Check for Updates	
Usage My Verizon	Support	Detect Device
Available Network	Device Support Page	Signal
Verizon Wireless -	About VZAccess Manager	F ccl
	WWAN Device Info	CALL .

© 2012 Verizon Wireless. All company names, trademarks, logos, and copyrights not property of Verizon Wireless are property of their respective owners. All rights reserved.

VPN compatibility issue with Microsoft Windows[®] 7 Windows Mobile Broadband





3. Verify that the modem has software version L0290VWBB12F.248 by selecting "Help->WWAN Device info."

VZAccess Manager				1	_ 2 0 💌
File View Tools Options H	lelp			verizon	
Natworks	Contents	F	1		
	Check for Update	es	ocations		
Usage My Verizon	Support				Detect Device
Available Network	Device Support P	Page		Signal	
Verizon Wireless -	About VZAccess	Manager		Fa ti	
	WWAN Device In	nfo			
MOMANU	Davias Info			-X -	
WWWAN	Device Into				
Hardwa	are information:				
Manu	facturer	PCD		A	
Mode	4	UML290VW			
Mode	m Name	PANTECH UML2	90	-	
Firmw	are Version	L0290VWBB12F	.248	-	
Hardv	vare Version	REV_03			

4. After verifying the above, go to "Options->Preferences->Connect". Select "LAN Adapter" in the "Device operating mode" drop down box.

VPN compatibility issue with Microsoft Windows[®] 7 Windows Mobile Broadband



Preferences - Connect	-	at the second	? ×
Connect Connect Caunch Connect Launch Connect Caunch Connect Caunch Connect Caunch Connect Caunch Connect Caunch Connect Caunch Connect Caunch Connect Caunch Connect Connect Caunch Connect C	Connect	tivity options Device operating mode: Windows Mobile Broadband LAN Adapter Windows Mobile Broadband LAN Adapter - Manually connect Auto-connect Wi-Fi Auto-connect precedence: Wi-Fi Connections WWAN Connections WWAN Connections Automatically switch from WW APN: VZWINTERNET OK	Move Up Move Down AN to Wi-Fi Restore Default Cancel

Click "Yes" to continue and wait for the mode switch to finish. The modem will reboot and be redetected by windows, please be patient.

5. After the mode switch has completed successfully, click "OK" to close VZAccess Manager.



- Launch VZAccess Manager again and verify that the modem is now operating in LAN Adapter mode.
 Note: VZAccess Manager will no longer be using the native Windows 7 Mobile Broadband APIs; instead the modem will appear to Windows as a LAN Adapter resolving certain VPN compatibility and connectivity issues.
- 7. Establish a connection and test VPN connectivity.

© 2012 Verizon Wireless. All company names, trademarks, logos, and copyrights not property of Verizon Wireless are property of their respective owners. All rights reserved.