























































Category	Command	Shortcut(s)	Search Shortcut
File	 New..	Ctrl+N	
File	 Open..	Ctrl+O	
File	 Close..	Ctrl+W	
File	 Save..	Ctrl+S	
File	 Print..	Ctrl+P	
File	Browse Recent Documents..	R	
Edit	 Undo..	Ctrl+Z	
Edit	 Redo..	Ctrl+Y	
Edit	Repeat Last Command..	Enter	
Edit	 Select All..	Ctrl+A	
Edit	 Cut..	Ctrl+X	
Edit	 Copy..	Ctrl+C	
Edit	 Paste..	Ctrl+V	
Edit	 Delete..	Delete	
Edit	 Rebuild..	Ctrl+B	r
Edit	 Copy Appearance..	Ctrl+Shift+C	
Edit	 Paste Appearance..	Ctrl+Shift+V	
View	 Redraw..	Ctrl+R	
View	 Orientation..	SpaceBar	
View	 Zoom to Fit..	F	zf
View	 Planes..	Alt+P	
View	 Sketches..	Shift+S	
View	 Sketch Relations..	Shift+R	
View	 Quick Snaps..	F3	
View	 Full Screen..	F11	
View	FeatureManager Tree Area..	F9	
View	Toolbars..	F10	
View	Task Pane..	Ctrl+F1	
Insert	 Flex..	Shift+F	
Tools	 Magnified Selection..	G	
Tools	 Select All..	Ctrl+A	
Tools	 Line..	L	l
Tools	 Smart..	D	
Tools	 Measure..	Shift+M	
Window	Close All..	Alt+X	
Help	 SOLIDWORKS Help..	H	
Help	 Knowledge Base..	K	
Help	 Community Forum..	O	
Help	 Commands..	W	
Help	 Files and Models..	I	
Others	 Front	Ctrl+1	
Others	 Back	Ctrl+2	
Others	 Left	Ctrl+3	
Others	 Right	Ctrl+4	
Others	 Top	Ctrl+5	
Others	 Bottom	Ctrl+6	
Others	 Isometric	Ctrl+7	
Others	 Normal To	Ctrl+8,F4	
Others	Command option toggle	A	
Others	Expand/Collapse Tree	C	
Others	Collapse all Items.	Shift+C	
Others	 Filter Edges	E	
Others	Find/Replace	Ctrl+F	
Others	Show Flat Tree View	Ctrl+T	

Category	Command	Shortcut(s)	Search Shortcut
Others	Next Edge	N	
Others	Force Regen	Ctrl+Q	
Others	Shortcut Bar	S	
Others	 Filter Vertices	V	
Others	Hide/Show Display Pane.	F8	
Others	 Toggle Selection Filter Toolbar	F5	
Others	 Toggle Selection Filters	F6	
Others	 Spell Checker	F7	
Others	Next Command Manager Tab	Ctrl+Next	
Others	Previous Command Manager Tab	Ctrl+Prior	
Others	 View Selector	Ctrl+SpaceBar	
Others	Scroll to FeatureManager tree top	Home	
Others	Scroll to FeatureManager tree bottom	End	
Others	 Filter Faces	X	
Others	Accept Edge	Y	
Others	Zoom Out	Z	
Others	Zoom In	Shift+Z	
Others	 Previous View	Ctrl+Shift+Z	
Others	Toggle Notes Upper Case.	Shift+F3	
Others	Select Annotation View	SingleQuote	
Others	 Normal To	Ctrl+8,F4	
Others	 Hide the Hovered-over Component	TAB	
Others	 Show the Hovered-over Component	Shift+TAB	
Search	 Search SOLIDWORKS Help	H	
Search	 Search Knowledge Base	K	
Search	 Search Community Forum	O	
Search	 Search Commands	W	
Search	 Search Files and Models	I	