



Assembly Serial #	J129236
Test Date / Time	7/7/2023 15:10
Tester Certification #	6-282
Assembly Test Results	<input checked="" type="checkbox"/> Pass <input type="checkbox"/> *Fail
	<input type="checkbox"/> Under Suspension - Process Immediately

Denver Water Backflow Assembly Test & Maintenance Report (please print CLEARLY with BLOCK LETTERING)

Account	Business Name: CLERMONT TOWNHOMES				
	Facility Address: 1865 S CLERMONT			City: DENVER	
	Contact Person: LORI			Phone: (720) 220-1391	
Assembly	Make: Febco Model: 825Y		Type Of Use		Orientation
	Type: <input checked="" type="checkbox"/> RP <input type="checkbox"/> DC <input type="checkbox"/> PVB <input type="checkbox"/> Air Gap		<input type="checkbox"/> Domestic		Inlet
	Size: 1" Date Installed: _____		<input type="checkbox"/> Fire <input type="checkbox"/> Glycol		Outlet
	<input type="checkbox"/> New <input checked="" type="checkbox"/> Existing		<input checked="" type="checkbox"/> Irrigation		<input type="checkbox"/> Horizontal <input type="checkbox"/>
	Previous Assembly #:		<input type="checkbox"/> Recycled		<input checked="" type="checkbox"/> Vertical Up <input type="checkbox"/>
	Location: NO. SIDE OF BLDG. OUTSIDE		Supplies: _____		<input type="checkbox"/> Vertical Down <input checked="" type="checkbox"/>
Testing & Maintenance	Line PSI: 95	Initial Test	Repairs		Retest
	Check Valve #1 (RP, DC, PVB)	7.5			
	Check Valve #2 (RP, DC)	Tight			
	Relief Valve (RP)	2.3			
	Buffer (RP)				
	Air Inlet (PVB)				
	Test Procedure: ABPA USC 10th Edition		ASSE		
Comments	Comments/Issues:				
Test Kit	Test Kit Make: Midwest		Model: 845-2		
	Serial #: 10192200		Last Calibration Date: 2200 - 10/10/2022		
Tester	Testing Company: Backflow Consulting Testing and Repair, Inc				
	Tester Name: Jesse Bockhouse			Phone: (303) 537-0126	
	Signature:			Certificate Expiration Date: 5/31/2024	

Testing Company: Submit by e-mail (preferred) to CrossConnectionControl@denverwater.org, type "Backflow Test Reports" in the subject line OR submit by Fax to (303) 794-8325.

* FAILED test results must be reported to Denver Water within 24 hours of failure at (303) 628-5969.



Assembly Serial #	J134354
Test Date / Time	7/7/2023 15:11
Tester Certification #	6-282
Assembly Test Results	<input checked="" type="checkbox"/> Pass <input type="checkbox"/> *Fail
	<input type="checkbox"/> Under Suspension - Process Immediately

Denver Water Backflow Assembly Test & Maintenance Report (please print CLEARLY with BLOCK LETTERING)

Account	Business Name: CLERMONT TOWNHOMES				
	Facility Address: 4472 E BAILS PL			City: DENVER	
	Contact Person: LORI		Phone: (720) 220-1391		
Assembly	Make: Febco Model: 825Y		Type Of Use		Orientation
	Type: <input checked="" type="checkbox"/> RP <input type="checkbox"/> DC <input type="checkbox"/> PVB <input type="checkbox"/> Air Gap		<input type="checkbox"/> Domestic		Inlet
	Size: 1" Date Installed: _____		<input type="checkbox"/> Fire <input type="checkbox"/> Glycol		Outlet
	<input type="checkbox"/> New <input checked="" type="checkbox"/> Existing		<input checked="" type="checkbox"/> Irrigation		<input type="checkbox"/> Horizontal <input type="checkbox"/>
	Previous Assembly #:		<input type="checkbox"/> Recycled		<input checked="" type="checkbox"/> Vertical Up <input type="checkbox"/>
	Location: OUTSIDE NORTH SIDE OF BLDG		Supplies: _____		<input type="checkbox"/> Vertical Down <input checked="" type="checkbox"/>
Testing & Maintenance	Line PSI: 95	Initial Test	Repairs		Retest
	Check Valve #1 (RP, DC, PVB)				7.6
	Check Valve #2 (RP, DC)				Tight
	Relief Valve (RP)	0.0	Cleaned		3.0
	Buffer (RP)				
	Air Inlet (PVB)				
	Test Procedure: ABPA USC 10th Edition		ASSE		
Comments	Comments/Issues:				
Test Kit	Test Kit Make: Midwest		Model: 845-2		
	Serial #: 10192200		Last Calibration Date: 2200 - 10/10/2022		
Tester	Testing Company: Backflow Consulting Testing and Repair, Inc				
	Tester Name: Jesse Bockhouse		Phone: (303) 537-0126		
	Signature:		Certificate Expiration Date: 5/31/2024		

Testing Company: Submit by e-mail (preferred) to CrossConnectionControl@denverwater.org, type "Backflow Test Reports" in the subject line OR submit by Fax to (303) 794-8325.

* **FAILED** test results **must** be reported to Denver Water within 24 hours of failure at (303) 628-5969.



Assembly Serial #	J133927
Test Date / Time	7/7/2023 15:42
Tester Certification #	6-282
Assembly Test Results	<input checked="" type="checkbox"/> Pass <input type="checkbox"/> *Fail
	<input type="checkbox"/> Under Suspension - Process Immediately

Denver Water Backflow Assembly Test & Maintenance Report (please print CLEARLY with BLOCK LETTERING)

Account	Business Name: CLERMONT TOWNHOMES				
	Facility Address: 4461 E JEWELL AVE			City: DENVER	
	Contact Person: LORI		Phone: (720) 220-1391		
Assembly	Make: Febco Model: 825Y		Type Of Use		Orientation
	Type: <input checked="" type="checkbox"/> RP <input type="checkbox"/> DC <input type="checkbox"/> PVB <input type="checkbox"/> Air Gap		<input type="checkbox"/> Domestic		Inlet
	Size: 1" Date Installed: _____		<input type="checkbox"/> Fire <input type="checkbox"/> Glycol		Outlet
	<input type="checkbox"/> New <input checked="" type="checkbox"/> Existing		<input checked="" type="checkbox"/> Irrigation		<input type="checkbox"/> Horizontal <input type="checkbox"/>
Previous Assembly #:		<input type="checkbox"/> Recycled		<input checked="" type="checkbox"/> Vertical Up <input type="checkbox"/>	
Location: OUTSIDE SOUTH SIDE OF BLDG		Supplies: _____		<input type="checkbox"/> Vertical Down <input checked="" type="checkbox"/>	
Testing & Maintenance	Line PSI: 95	Initial Test	Repairs		Retest
	Check Valve #1 (RP, DC, PVB)	Leak	Cleaned		9.9
	Check Valve #2 (RP, DC)				Tight
	Relief Valve (RP)				2.3
	Buffer (RP)				
	Air Inlet (PVB)				
Test Procedure: ABPA USC 10th Edition			ASSE		
Comments	Comments/Issues:				
Test Kit	Test Kit Make: Midwest		Model: 845-2		
	Serial #: 10192200		Last Calibration Date: 2200 - 10/10/2022		
Tester	Testing Company: Backflow Consulting Testing and Repair, Inc				
	Tester Name: Jesse Bockhouse		Phone: (303) 537-0126		
	Signature:		Certificate Expiration Date: 5/31/2024		

Testing Company: Submit by e-mail (preferred) to CrossConnectionControl@denverwater.org, type "Backflow Test Reports" in the subject line OR submit by Fax to (303) 794-8325.

* **FAILED** test results **must** be reported to Denver Water within 24 hours of failure at (303) 628-5969.



Assembly Serial #	J132566
Test Date / Time	_____
Tester Certification #	_____
Assembly Test Results	<input type="checkbox"/> Pass <input type="checkbox"/> *Fail
	<input type="checkbox"/> Under Suspension - Process Immediately

Denver Water Backflow Assembly Test & Maintenance Report (please print CLEARLY with BLOCK LETTERING)

Account	Business Name: CLERMONT TOWNHOMES				
	Facility Address: 4473 E JEWELL AVE			City: DENVER	
	Contact Person: LORI		Phone: (720) 220-1391		
Assembly	Make: Febco Model: 825Y		Type Of Use		Orientation
	Type: <input type="checkbox"/> RP <input type="checkbox"/> DC <input type="checkbox"/> PVB <input type="checkbox"/> Air Gap		<input type="checkbox"/> Domestic		<input type="checkbox"/> Inlet <input type="checkbox"/> Outlet
	Size: 1" Date Installed: _____		<input type="checkbox"/> Fire <input type="checkbox"/> Glycol		<input type="checkbox"/> Horizontal <input type="checkbox"/>
	<input type="checkbox"/> New <input type="checkbox"/> Existing		<input type="checkbox"/> Irrigation		<input type="checkbox"/> Vertical Up <input type="checkbox"/>
Previous Assembly #:		<input type="checkbox"/> Recycled		<input type="checkbox"/> Vertical Down <input type="checkbox"/>	
Location: OUTSIDE SOUTH SIDE OF BLDG		Supplies: _____			
Testing & Maintenance	Line	Initial Test	Repairs		Retest
	PSI:				
	Check Valve #1 (RP, DC, PVB)				
	Check Valve #2 (RP, DC)				
	Relief Valve (RP)				
	Buffer (RP)				
Air Inlet (PVB)					
Test Procedure: ABPA			ASSE		
Comments	Comments/Issues: No water to assembly				
Test Kit	Test Kit Make: Midwest		Model: _____		
	Serial #: _____		Last Calibration Date: _____		
Tester	Testing Company: Backflow Consulting Testing and Repair, Inc				
	Tester Name: Jesse Bockhouse		Phone: (303) 537-0126		
	Signature: _____		Certificate Expiration Date: _____		

Testing Company: Submit by e-mail (preferred) to CrossConnectionControl@denverwater.org, type "Backflow Test Reports" in the subject line OR submit by Fax to (303) 794-8325.

* **FAILED** test results **must** be reported to Denver Water within 24 hours of failure at (303) 628-5969.



Assembly Serial #	J009313
Test Date / Time	7/7/2023 15:44
Tester Certification #	6-282
Assembly Test Results	<input checked="" type="checkbox"/> Pass <input type="checkbox"/> *Fail
	<input type="checkbox"/> Under Suspension - Process Immediately

Denver Water Backflow Assembly Test & Maintenance Report (please print CLEARLY with BLOCK LETTERING)

Account	Business Name: CLERMONT TOWNHOMES				
	Facility Address: 1885 S CLERMONT ST			City: DENVER	
	Contact Person: LORI		Phone: (720) 220-1391		
Assembly	Make: Febco Model: 825Y		Type Of Use		Orientation
	Type: <input checked="" type="checkbox"/> RP <input type="checkbox"/> DC <input type="checkbox"/> PVB <input type="checkbox"/> Air Gap		<input type="checkbox"/> Domestic		Inlet
	Size: 1" Date Installed: _____		<input type="checkbox"/> Fire <input type="checkbox"/> Glycol		Outlet
	<input type="checkbox"/> New <input checked="" type="checkbox"/> Existing		<input checked="" type="checkbox"/> Irrigation		<input type="checkbox"/> Horizontal <input type="checkbox"/>
	Previous Assembly #:		<input type="checkbox"/> Recycled		<input checked="" type="checkbox"/> Vertical Up <input type="checkbox"/>
	Location: OUTSIDE OF THE SO. SIDE OF BLDG.		Supplies: _____		<input type="checkbox"/> Vertical Down <input checked="" type="checkbox"/>
Testing & Maintenance	Line PSI: 90	Initial Test	Repairs		Retest
	Check Valve #1 (RP, DC, PVB)	8.5			
	Check Valve #2 (RP, DC)	Tight			
	Relief Valve (RP)	2.9			
	Buffer (RP)				
	Air Inlet (PVB)				
	Test Procedure: ABPA USC 10th Edition		ASSE		
Comments	Comments/Issues:				
Test Kit	Test Kit Make: Midwest		Model: 845-2		
	Serial #: 10192200		Last Calibration Date: 2200 - 10/10/2022		
Tester	Testing Company: Backflow Consulting Testing and Repair, Inc				
	Tester Name: Jesse Bockhouse		Phone: (303) 537-0126		
	Signature:		Certificate Expiration Date: 5/31/2024		

Testing Company: Submit by e-mail (preferred) to CrossConnectionControl@denverwater.org, type "Backflow Test Reports" in the subject line OR submit by Fax to (303) 794-8325.

* **FAILED** test results **must** be reported to Denver Water within 24 hours of failure at (303) 628-5969.



Assembly Serial #	J127405
Test Date / Time	7/7/2023 15:12
Tester Certification #	6-282
Assembly Test Results	<input checked="" type="checkbox"/> Pass <input type="checkbox"/> *Fail
	<input type="checkbox"/> Under Suspension - Process Immediately

Denver Water Backflow Assembly Test & Maintenance Report (please print CLEARLY with BLOCK LETTERING)

Account	Business Name: CLERMONT TOWNHOMES				
	Facility Address: 4460 E BAILS PL			City: DENVER	
	Contact Person: LORI		Phone: (720) 220-1391		
Assembly	Make: Febco Model: 825Y		Type Of Use		Orientation
	Type: <input checked="" type="checkbox"/> RP <input type="checkbox"/> DC <input type="checkbox"/> PVB <input type="checkbox"/> Air Gap		<input type="checkbox"/> Domestic		Inlet
	Size: 1" Date Installed: _____		<input type="checkbox"/> Fire <input type="checkbox"/> Glycol		Outlet
	<input type="checkbox"/> New <input checked="" type="checkbox"/> Existing		<input checked="" type="checkbox"/> Irrigation		<input type="checkbox"/> Horizontal <input type="checkbox"/>
Previous Assembly #:		<input type="checkbox"/> Recycled		<input checked="" type="checkbox"/> Vertical Up <input type="checkbox"/>	
Location: OUTSIDE NORTH SIDE OF BLDG		Supplies: _____		<input type="checkbox"/> Vertical Down <input checked="" type="checkbox"/>	
Testing & Maintenance	Line PSI: 95	Initial Test	Repairs		Retest
	Check Valve #1 (RP, DC, PVB)	6.6			
	Check Valve #2 (RP, DC)	Tight			
	Relief Valve (RP)	2.7			
	Buffer (RP)				
	Air Inlet (PVB)				
Test Procedure: ABPA USC 10th Edition			ASSE		
Comments	Comments/Issues:				
Test Kit	Test Kit Make: Midwest		Model: 845-2		
	Serial #: 10192200		Last Calibration Date: 2200 - 10/10/2022		
Tester	Testing Company: Backflow Consulting Testing and Repair, Inc				
	Tester Name: Jesse Bockhouse			Phone: (303) 537-0126	
	Signature:		Certificate Expiration Date: 5/31/2024		

Testing Company: Submit by e-mail (preferred) to CrossConnectionControl@denverwater.org, type "Backflow Test Reports" in the subject line OR submit by Fax to (303) 794-8325.

* **FAILED** test results **must** be reported to Denver Water within 24 hours of failure at (303) 628-5969.